North America Emission Control Area Fuel Oil Non-Availability Report
ECA0100

1 2 3

##(Include Double Pound for comments, not form fields)

##Report Form ID Ship Operator Name Vessel Name

EC A0100 EP FLOPEC STENA CHIRON

4 5 6 7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

9282625

BS BHS 044 6/1/2015 PAL

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption

PAL LONG BEACH NA

Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted	Date of Entry in the ECA
NA	NA	6/1/2015

16	15	14
ojected Hours on Main Propulsion	Sulfur Content of Non-Compliant Fuel Oil	Time of Entry in the ECA
16	0.9	12:00

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC?

PAL NO N/A

20 21 22

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

N/A LONG BEACH YES

23 24

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

YES TBC

25 26

27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

8/1/2015

8:00 YES

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

9 10 NO

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail

1 RAQUEL ALVEAR

OPERACIONES@FLOPEC.COM.EC

Designated Corporate Official Phone Number

593 9 8 453 0301

Description of Actions to Achieve Compliance

FOR YOUR INFORMATION VESSEL WAS INSTRUCTED FIRST TO DISCHARGE ALL HER CARGO AT PAL, AND SHE HAD ENOUGH MGO TO PERFORM THAT OPERATION, BUT CHARTERERS CHANGED INSTRUCTIONS ONCE VESSEL ARRIVED TO PAL AND ADVISED TO PROCEED FIRST TO LONG BEACH TO PERFORM 2 DISCHARGE OPERATIONS THERE. DUE TO THE